



4701 Massachusetts Avenue
 Indianapolis, IN 46218
 800-624-1895 (317) 549-4290
 Fax: (317) 549-4295

MATERIAL SAFETY DATA SHEET

ISSUED DATE 11-22-85 REVISED DATE 9-30-09

I. IDENTIFICATION

MANUFACTURER'S NAME		Mi-Tech Metals, Inc.		EMERGENCY TELEPHONE NO.		(317) 549-4290	
ADDRESS		4701 Massachusetts Avenue - Indianapolis, IN 46218					
CHEMICAL NAME AND SYNONYMS		Tungsten, Silver		TRADE NAME AND SYNONYMS		SW65	
C.A.S. NO.	NIF	T.S.C.A. NO.	NIF	FORMULA	W-Ag		
DEPARTMENT OF TRANSPORTATION	HAZARD CLASSIFICATION	NIF		U.N. NO.	NIF		
	SHIPPING NAME	SW65 Silver Tungsten					

II. INGREDIENTS

MATERIAL	%	TLV (Units)	C.A.S. NO.	NFPA RATING
Tungsten	65	5 MG/M ³	7440-33-7	
Silver	35	0.1 MG/M ³	7440-22-4	

REPORT ALL INGREDIENTS ≥3%; IF HAZARDOUS, REPORT ≥1%; SPECIAL HAZARDOUS SUBSTAND ≥0.01%

III. PHYSICAL DATA

BOILING POINT, 760mm Hg 101.325 kPa	Tungsten - 5660°C Silver - 1955°C	FREEZING POINT	N/A
SPECIFIC GRAVITY (H ₂ O=1)	14.5 g/cc	VAPOR PRESSURE AT 20°C	N/A
VAPOR DENSITY (AIR=1)	N/A	SOLUBILITY IN WATER, % BY WT.	Insoluble
APPEARANCE AND ODOR	Silver - No odor		

IV. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method Used)	Non-combustible	FLAMMABLE LIMITS LEL	N/A	UEL	N/A
EXTINGUISHING MEDIA					
SPECIAL FIRE FIGHTING PROCEDURES					
UNUSUAL FIRE AND EXPLOSION HAZARDS	Will oxidize at or about 1300°F				

V. REACTIVITY DATA

STABILITY			
UNSTABLE	STABLE	CONDITIONS	Keep away from strong acids.
	X	TO AVOID	
INCOMPATIBILITY (Materials to Avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS			

VI. HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	OSHA	Tungsten 5 MG/M ³ Silver 0.1 MG/M ³	ACGIH	Tungsten 5 MG/M ³ Silver 0.1 MG/M ³
ROUTES OF EXPOSURE (Check Those Which Apply)	EYE CONTACT	No	INHALATION	No
	SKIN CONTACT	X	INGESTION	No
SIGNS AND SYMPTOMS OF OVEREXPOSURE Silver can cause argyria or permanent pigmentation of the skin, from repeated exposures over a considerable period of time where alloy is in the form of finely divided dust particles.				
EFFECTS OF OVEREXPOSURE				
ACCUTE				
CHRONIC NIF (No information found)				
HAS IOSHA FOUND THIS MATERIAL TO BE A POTENTIAL CARCINOGEN? YES NO X				
EMERGENCY FIRST AID PROCEDURES				

VII. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELATED OR SPILLED	
WASTE DISPOSAL METHOD	Re-cycle all scrap and machine turnings.
DISPOSER MUCH COMPLY WITH FEDERAL, STATE AND LOCAL DISPOSAL OR DISCHARGE LAWS.	

VIII. SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify Type)		Use NIOSHA/MSHA approved type respirator for dusting conditions	
VENTILATION	LOCAL EXHAUST	Recommended	SPECIAL NIF
	MECHANICAL (General)	NIF	OTHER NIF
PROTECTIVE GLOVES		None	EYE PROTECTION Use safety eyewear
OTHER PROTECTIVE EQUIPMENT		None	

IX. SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	Store in cool, dry, well ventilated area. Separate from acids and alkalis.
OTHER PRECAUTIONS	

DISCLAIMER OF LIABILITY

As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of the material. Information contained herein is believed to be true and accurate but all statements or suggestions are made without any warranty, express or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof.

Form # 137

Rev. B
03/01/06
Page 2 of 2